

NOTES:

1. MARK ALL ELECTRICAL HARDWARE WITH IDENTIFICATION NOS AS SHOWN USING RUBBER STAMP & EPOXY INK.
2. APPLY ONE COAT OF PRIME PAINT AND TWO COATS OF FINISH ENAMEL PER SPECIFICATION NO.611 EXCEPT WHERE NOTED
3. APPLY FINISH COAT OF BLACK VELVET ON ALL SURFACES NOTED AND ALL SURFACES FALLING WITHIN OR ADJACENT TO LIGHT PATH.
4. PROTECT ALL UNPAINTED SURFACES WITH BRAYCOAT PT #103 RUST PREVENTATIVE COMPOUND BEFORE SHIPPING.
5. FLATS ON OUTBOARD SHAFTS OF MOTORS TO RECEIVE ITEMS 115 (CRANK HANDLES) FOR MANUAL CLOSING OF P.M. COVER (SHT 3)

NEXT ASSY: 2150.280E002

NATIONAL OPTICAL ASTRONOMY OBSERVATORIES

NEXT ASSEMBLY: 2150.280E002

NAME: ASSY CENTER SECTION & P.M. COVER

REF FLE: 1176

SCALE: 1/16 & NOTED

AUTOCAD r.14

R. STRONG

2150.281E002

REV: P

SHEET 1 OF 5